DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015667 Address: 333 Burma Road **Date Inspected:** 13-Jul-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Liu Hua Jie. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Mr. Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. This QA Inspector made the following observations:

OBG Trial Assembly Yard:

OBG Seg 9CE to Seg 9DE:

This QA Inspector observed the following work in progress:

The Shielded Metal Arc Welding (SMAW) process of weld joint nos: DP699-001-019, 020 & 021. The welder was identified as 054467. The ZPMC Quality Control (QC) was identified as Wang Liang. The welding variables recorded by QC appeared to comply with the WPS-B-T-3213-B-U3b.

The SMAW process of weld no's: DP712-001-019, 020 & 021. The welder was identified as 048659. The ZPMC QC was identified as Wang Liang. The welding variables recorded by QC appeared to comply with the WPS-B-T-3213-B-U3b.

The SMAW process of weld no's: OBE9C-004 & 005. The welders were identified as 067665 & 067942. The ZPMC QC was identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with the

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

WPS-B-P-2214-B-U2-FCM-1.

OBG Seg 9CW:

This QA Inspector observed ZPMC personnel performing the heat straightening operation on Floor Beam Flange (at PP77). The Heat Straightening was performed according to Heat Straightening Request (HSR) no: HSR1(B)-8722 Rev-0, Dated: 07/02/10. The ZPMC QC is identified as Zhang Qiang. HSR was performed to correct the weld distortion on the Floor Beam Flange. See attached photo for further details.

Bay 5:

Notification no: 006189.

This QA inspector performed Magnetic Particle Testing (MPT) of approximately 15% of an area that has been previously tested and accepted by ZPMC QC personnel. This QA Inspector generated an MPT report for this date. The member(s) are identified as OBG component – Traveler Rail. The weld designations reviewed were as follows:

- 1) 10TR2-012-005, 006, 007, 013 & 014.
- 2) 10TR1-013-005, 006, 007, 013 & 014.
- 3) 11TR3-016-005, 006, 007, 013 & 014.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



Summary of Conversations:

No significant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT (Continued Page 3 of 3)

Inspected By:	Wadkar, Sailesh	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer